




Wiring Assembly Instructions

0883010-13 Contact, ITA, Mini-Coax, JOY14, 50 Ohm.



Fig. A. (Contact Sub-Assembly)



Contact Sub-Assembly Piece Parts.

**Contact Crimp Information Table**

Wire Type	Wire Awg.	Strip Length In Inches	Crimp Tool	Hex Die Set	Indicator	Selector No.	Heat-shrink Length X Dia.
JOY 14	30	A) 3/16 B) 13/64 C) 3/8	452300	452309	I	N/A	5/8 X 3/32

**Test Requirements**

Test Type	Voltage (Hi-pot Only)	Pull Test	Depth Gauge	Marker Settings
Hi-pot	500V DC	1.5lbs	412656	76 - 91

**NOTE 1:** Refer to **IPC/WHMA-A-620A** standard (Ch. 11.1.2) for cable lengths, measurements and tolerance.

**NOTE 2:** Overall length of cable should be less 3/8" to compensate for the contact attachment.

**STEP 1)** From the "Contact Crimp Information" Table, use the crimp tool and hex die set listed.

**STEP 2)** Ensure hex die, is set to correct indicator as listed in "Contact Crimp Information" Table.

**NOTE:** Refer to Fig. B for reference




Fig. B.

Detail A.

**STEP 3)** Using a ruler along with wire strippers, strip the cable to the dimensions in the "Strip Length" column. Example of stripped wire shown below in Fig. C




Fig. C.

**STEP 4)** Slide crimp ring over cable. Pull shield back over the cable outer jacket as shown below in Fig. D

**NOTE:** Ensure that no strand of Center Conductor contacts the shield to prevent shorts.



Fig. D

**STEP 5)** Tin center pin and center wire. Slide Teflon over dielectric. Insert cable center wire into center pin and solder in place. Fig. E. and F



Fig. E



Fig. F

**STEP 6)** Ensure dielectric is fully seated in shell. Slide shell assembly onto center conductor/cable sub-assembly until fully seated as shown in Fig. G.



Fig. G

**STEP 7)** Evenly form shielding over contact as shown in Fig. H.



Fig. H

**STEP 8)** Slide crimp ring over shield and up to contact until firmly seated in Fig. J.



Fig. J.

**STEP 9)** Inspect contact/cable assembly using depth gauge listed in "Test Requirements" Table. **Fig. K.**

**NOTE:** Calibrate gauge using reference sheet **IN 412656** (Instructions for calibrating Depth Gauge) before using.



Fig. K.

**STEP 10)** Test contact by inserting contact/cable assembly fully into test gauge, until seated firmly. **Fig. L.**

**STEP 11)** Gently tap top of pin gauge to ensure that gauge is seated fully to bottom of center contact pin.

**STEP 12)** Hold contact/cable assembly, and test gauge firmly, proceed to take measurement. **Fig. L.**



Fig. L.

**STEP 13)** Results should be between the "Marker Settings". Listed on the "Test Requirements" Table.

**NOTE:** Do not proceed to step 15 if results are unacceptable.(Repeat steps **3** through **13**).

**STEP 14)** Use crimp tool, and crimp large diameter of crimp ring in location **(A)** of hex die **Fig. M.**

**STEP 15)** Crimp small diameter of crimp ring in location **(C)** of hex dies. **Fig. N.**

**NOTE:** Make sure the contact seats properly in the stops aligned with locations on hex die **Figs. M.** and **N** details.





Fig. M. (Front View)



Detail (Back View)





Fig. N. (Front View)



Detail (Back View)

**STEP 16)** Perform a "pull and return test" as per **IPC/WHMA-A-620A** standard (Ch. 19.7.2.1) utilizing a pull force of 1.5lbs.

**STEP 17)** Gauge crimped contact/cable assembly again using the depth gauge (steps 10 to 16). The reading should still be within range.

**STEP 18)** Perform a "Hi-pot" test to the settings listed in "Test requirements". If a "pass" test occurs proceed to next step.

**STEP 29)** Shrink heat-shrink onto crimp ring, to match the image below in **Fig. P**, to complete cable assembly.



Fig. P.

**NOTE:** Shrink-tube is to provide strain-relief.