




Wiring Assembly Instructions

**0883010-10 Contact, ITA, Mini-Coax, RG178, 50 Ohms.**



**Fig. A. (Contact Sub-Assembly)**



Contact Sub-Assembly Piece Parts.

**Contact Crimp Information Table**

Wire Type	Wire Awg.	Strip Length In Inches	Crimp Tool	Hex Die Set	Indicator	Selector No.	Heat-shrink Length X Dia.
RG178	30	A) 3/16" B) 7/32" C)13/32"	452300	452312	I	N/A	5/8 X 3/32

**Test Requirements**

Test Type	Voltage (Hi-pot Only)	Pull Test	Depth Gauge	Marker Settings
Hi-pot	500V DC	1.5lbs	412656	70 - 90



**NOTE 1:** Refer to **IPC/WHMA-A-620A** standard (Ch. 11.1.2) for cable lengths, measurements and tolerance.

**NOTE 2:** Overall length of cable should be less 3/8" to compensate for the contact attachment.

**STEP 1)** From the "Contact Crimp Information" Table, use the crimp tool and hex die set listed.

**STEP 2)** Ensure hex die, is set to correct indicator as listed in "Contact Crimp Information" Table.


**NOTE:** Refer to **Fig. B** for reference.



**Fig. B. (452300)**

**Detail A. (452312)**


**STEP 3)** Using a ruler along with wire strippers or automatic wire stripping machine, strip the cable to the dimensions in the "Strip Length" column. Example of stripped wire shown below in **Fig. C.**



**Fig. C.**


**STEP 4)** Slide crimp ring over cable. Pull shield back over the cable outer jacket and slide Teflon over dielectric as shown below in **Fig. D.**

**NOTE:** Ensure that no strand of Center Conductor contacts the shield to prevent shorts.




**Fig. D.**

**STEP 5)** Tin center pin and center wire. Insert cable center wire into center conductor and solder in place. **Fig. E. and F.**




**Fig. E.**



**Fig. F.**

**STEP 6)** Ensure dielectric is fully seated in shell. Slide shell assembly onto center conductor/cable sub-assembly until fully seated as shown in **Fig. G.**



**Fig. G.**

**STEP 7)** Evenly form shielding over contact as shown in **Fig. H.**




Fig. H.

**STEP 8)** Slide crimp ring over shield and up to contact until firmly seated in Fig. J.




Fig. J.

**STEP 9)** Inspect contact/cable assembly using depth gauge listed in "Test Requirements" Table. Fig. K.

**NOTE:** Calibrate gauge using reference sheet IN 412656 (Instructions for calibrating Depth Gauge) before using.



Fig. K.

**STEP 10)** Test contact by inserting contact/cable assembly fully into test gauge, until seated firmly. Fig. L.

**STEP 11)** Gently tap top of pin gauge to ensure that gauge is seated fully to bottom of center contact pin.

**STEP 12)** Hold contact/cable assembly, and test gauge firmly, proceed to take measurement as per Fig. L.



**STEP 13)** Results should be between the "Marker Settings". Listed on the "Test Requirements" Table.

**NOTE:** Do not proceed to step 15 if results are unacceptable. (Repeat steps 3 through 13).

**STEP 14)** Use crimp tool, and crimp large diameter of crimp ring in location (A) of hex die Fig. M.

**STEP 15)** Crimp small diameter of crimp ring in location **(C)** of hex die. **Fig. N.**


**NOTE:** Make sure the contact seats properly in the stops aligned with locations on hex die **Figs. M** and **N** details.




**Fig. M. (Front View)**



**Detail (Back View)**



**Fig. N. (Front View)**




**Detail (Back View)**

**STEP 16)** Perform a "pull and return test" as per **IPC/WHMA-A-620A** standard (Ch. 19.7.2.1) utilizing a pull force of 1.5lbs.

**STEP 17)** Gauge crimped contact/cable assembly again using the depth gauge (steps 9 to 15). The reading should still be within range.

**STEP 18)** Perform a "Hi-pot" test to the settings listed in "Test requirements". If a "pass" test occurs proceed to next step.

**STEP 19)** Shrink heat-shrink onto crimp ring, to match the image below in **Fig. P**, to complete cable assembly.



**Fig. P.**

**NOTE:** Shrink-tube is to provide strain-relief.