

COMMENTS / NOTES

Example of an APEX PCB Assembly using Headers to enable simple Contact replacement.

MAC-PANEL


WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
24/06/2014

DESCRIPTION

PCB_Example_APEX_156




Third Angle
Projection

DRAWING NO.

PCB_Example_APEX_156-C0

REVISION

SHEET
1 OF 4



COMMENTS / NOTES

Exploded view of parts

MACPANEL


WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
24/06/2014

DESCRIPTION

PCB_Example_APEX_156




Third Angle
Projection

DRAWING NO.

PCB_Example_APEX_156-C0

REVISION

SHEET
2 OF 4



COMMENTS / NOTES

Both Assembled and Exploded view of parts without Headers.
But difficult to remove contacts.

MAC-PANEL

WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
24/06/2014

DESCRIPTION

PCB_Example_APEX_156




Third Angle
Projection

DRAWING NO.

PCB_Example_APEX_156-CU

REVISION

SHEET
3 OF 4



COMMENTS / NOTES

Hole Layout for PCB Holes
View is Component side if used with 562602.




WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
24/06/2014

DESCRIPTION

APEX_260_PCB_Example-A



DRAWING NO.

APEX_156_PCB_Example-A-CU

REVISION

SHEET
4 OF 4