

COMMENTS / NOTES

Example of an APEX PCB Assembly using Headers to enable simple Contact replacement.

MACPANEL

WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
24/06/2014



Third Angle
Projection

DESCRIPTION

PCB_APEX_80-20


DRAWING NO.

PCB_APEX_80-20-CU

REVISION

0

SHEET
1 OF 4



COMMENTS / NOTES

Exploded view of parts

MACPANEL

WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
24/06/2014

DESCRIPTION

PCB_APEX_80-20



Third Angle
Projection


DRAWING NO.

PCB_APEX_80-20-CU

REVISION

0

SHEET
2 OF 4



COMMENTS / NOTES

Both Assembled and Exploded view of parts without Headers.
But difficult to remove contacts.



WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
24/06/2014



Third Angle
Projection

DESCRIPTION

PCB_APEX_80-20


DRAWING NO.

PCB_APEX_80-20-CU

REVISION


0


SHEET
3 OF 4



COMMENTS / NOTES

Hole Layout for PCB Holes
View is Component side if used with 562602.


 WWW.MACPANEL.COM

DRAWN BY
 davecooper
 DATE
 24/06/2014

 Third Angle
 Projection
 SHEET
 4 OF 4

DESCRIPTION
 APEX_80/20_PCB_Example
 DRAWING NO.
 APEX_80-20_PCB-CU
 REVISION
 0