


COMMENTS / NOTES

MAC-PANEL

WWW.MACPANEL.COM

DRAWN BY
bsalvatini

DATE
10/5/2020



DESCRIPTION

i3070 FlashPort PCBA, Fixture ITA





SHEET
1 OF 2

DRAWING NO.

565850

REVISION

B



A (1:1)

COMMENTS / NOTES


Wire handle notches removed per customer request 12/9/2021.
Material to be removed is marked as a two hatched regions.

MAC-PANEL

WWW.MACPANEL.COM

DRAWN BY
bsalvatini

DATE
10/5/2020



DESCRIPTION

i3070 Flash/Power Port PCBA,
Fixture Rail Modification

SHEET
2 OF 2

DRAWING NO.

E3701-21201-Modified

REVISION

B