

Product Update Notification

Product(s) affected: MAC Panel part number **753001-03**

Date of issue: 1st June 2023

Reason: Originally specified 96 position connector no longer available

New part number: **753001-04**

Form, fit, function (FFF)

Is there a change to form?

- Yes, the appearance of connector is different. Connector color changes from dark brown to cream

Is there a change to fit?

- No

Is there a change to function?

- No

Additional Information:



Appearance of 753001-03



Appearance of 753001-04