

## Product Update Notification

Product(s) affected:           MAC Panel part number **12114-02**

Date of issue:                    3rd August 2023

Reason:                            Originally specified 96 position connector no longer available

New part number:                **12114-03**

Form, fit, function (FFF)

Is there a change to form?

- Yes, the appearance of connector is different. Connector color changes from dark brown to cream

Is there a change to fit?

- No

Is there a change to function?

- No

Additional Information:



Appearance of 12114-02



Appearance of 12114-03