



## Product Update Notification

Product(s) affected:           MAC Panel part number **561313**

Date of issue:                    21<sup>st</sup> November 2023

Reason:                            Originally specified 96 position connector no longer available

New part number:                **564313**

### Form, fit, function (FFF)

Is there a change to form?

- Yes, the appearance of connector is different. Connector color changes from dark brown to cream. The rear side protrudes slightly more (see below for details)

Is there a change to fit?

- No
  - The above statement applies to the mating side of the connector. It is completely compatible with all ITA modules that currently mate with 561313.

Is there a change to function?

- No


**CORPORATE HEADQUARTERS**  
551 West Fairfield Road  
High Point, NC, United States 27263  
Phone: 336.861.3100  
Fax: 336.861.6280  
sales@macpanel.com

# MAC-PANEL

*Interconnect Solutions & Services*

Additional Information:

564313 (new module)



**CORPORATE HEADQUARTERS**

551 West Fairfield Road  
High Point, NC, United States 27263  
Phone: 336.861.3100  
Fax: 336.861.6280  
sales@macpanel.com