

## Product Update Notification

Product(s) affected:           MAC Panel part number **563700 Rev A**

Date of issue:                    1<sup>st</sup> January 2023


Reason:                            Product improvement for manufacturability, automated clipping

New part number:                **563700 Rev B**

### Form, fit, function (FFF)

Is there a change to form?

- Yes, the appearance of contact is different. Contact has a tapered nose versus a sharp shoulder.



Is there a change to fit?

- No

Is there a change to function?

- No


**MAC-PANEL**  
*Interconnect Solutions & Services*

Additional Information:



---

Appearance of 563700 Rev A



---

Appearance of 563700 Rev B

**CORPORATE HEADQUARTERS**  
551 West Fairfield Road  
High Point, NC, United States 27263  
Phone: 336.861.3100  
Fax: 336.861.6280  
[sales@macpanel.com](mailto:sales@macpanel.com)