

January 2009

CORPORATE HEADQUARTERS

551 W. Fairfield Rd. High Point, NC 27263 PH: +1 336.861.3100 FAX:+1 336.861.6280 sales@macpanel.com




Revision C

MAC PANEL LTD. - EUROPE


Clarence Rd., Bollington,
Macclesfield SK 10 5JZ United Kingdom
PH:+44 (0) 1625.572133
FAX:+44 (0) 1625.576166
salesuk@macpanel.com

Strain Relief Clip Part # 753001SR-02



Used with Series 75:
Receiver Side 753001
when using 7853103-01
and 7853109-01 only

96 Position Strain Relief Plate Part # 701096S



Used with Series 64 Connectors:

 Receiver Side
 70101900/P

 Receiver Side
 70125600R-01


 Receiver Side
 70132000R-01

 Receiver Side
 70109600R-01

 Receiver Side
 70101900/C

 Receiver Side
 70106400R-01

Strain Relief Plate Part # 11705-01





Used with Series 75 Connectors: Used with ARINC Connectors:

Receiver Side 753013 Receiver Side 753050G-01 753014 Receiver Side Receiver Side 753050G Receiver Side 753018 Receiver Side 753052 Receiver Side 753051G-01 Receiver Side 753013 Receiver Side 753053G Receiver Side 753051G 753014 Receiver Side

Receiver Side 753018

Strain Relief Backshell Part # 7853102-01







Works with the Following Series:

S/75 S/60 S/120 L2000 S/64 SCOUT

Used with these Connectors:
Receiver/ITA Side 7853103-01
Receiver/ITA Side 7853109-01


Strain Relief Clip Part# 753001SR - 01






Used with Series 75 Connector: Receiver Side 753001 when using 7853102-01

Strain Relief Clip Part # 753001SR-12







Works with the Following Series:

S/60 L2000 L80

Used with:
Receiver Side 603013 Module
when using
7853102-01 Backshell
and
7853109-01 96 Position Header





MPX Strain Relief Options

Used with MPX Connectors: 302000-05 302000-11

Part # 301011S-03




Part # 301011S-02



Part # 301011S-04



MPX Strain Relief Options



Used with Series MPX: 302000-06 and 302000-09

Part Number Description

301100-01 Corrugated Cable Protector

Length: 10 Ft.

Corrugated Cable Protector Length: 6 Ft. 301100-02

Proper Cable Strain Relief Using Cable Ties





Photo shows cable dressed at 90 degrees, attached to strain relief bracket using cable ties. Cable can also be dressed at 180 degrees. Care must be given when attaching cable ties to assure contact float is still maintained in the connector module.


Grounding Brackets



Part Number	Description
5510677	1" CTI Grounding Bracket
5510873	2" CTI Grounding Bracket
5510855	4" CTI Grounding Bracket
5510877	1" CASS Grounding Bracket
5510878	2" CASS Grounding Bracket
5510859	4" CASS Grounding Bracket


The pigtail lead attaches to the bracket with a 2-56 screw (not supplied).





200 Position Strain Relief Kit Part # 785030200K


Consist of: (1) 7850302S-200 Bracket (4) 7853150-01 Headers



Works with the Following Series:


S/60 SCOUT L2000 CTI L80

Strain Relief Clip Part # 753001SR-03



Upper Strain Relief Clip to be used instead of brackets

Strain Relief Clip Part # 753001SR-14



Holds the 7853109-01 to the 561413 module.

> SCOUT TITAN

