



COMMENTS / NOTES

USE SIGNAL CONTACT 0884012R-01 (4X) AND POWER CONTACT 5517701 (4X)  
 CABLING SHOULD BE STRAIN RELIEVED AFTER EXITING MODULE.

MACPANEL

WWW.MACPANEL.COM

DRAWN BY  
bsalvatini

DATE  
3/10/2021

DESCRIPTION

Module, Receiver, 4-Pos, High Power



SHEET  
1 OF 1

DRAWING NO.

562295

REVISION

A